

Inspection Photos

API#081-06592

Operator: HRM Resources

Inspection Number: 692402560

Inspection Date: 9/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View into Location from entry to Northwest.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06592



Photo#2:
Portion of what was location road. Eroding sediment has washed over road burying vegetation.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Re-vegetated area.

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06592



Photo#4:

Views over location vegetation. Russian thistle is the reddish hued plant.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06592



Photo#5:
Reference area.



Photo#6:
Reference area.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06592