

Inspection Photos

API: 071-06682

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/14/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020

Inspection Photos



Photo 1. Facing south toward the location. There is an active well at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020

Inspection Photos



Photo 2. Well sign is posted at meter shed for the [Champion #44-9 R](#) well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020

Inspection Photos



Photo 3. There is an unused riser which appears to be from the former meter shed of the [CHAMPION #44-9](#) well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020

Inspection Photos



Photo 4. The unused pipe riser will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020

Inspection Photos



Photo 5. Facing toward the offsite pit area. Additional seeding will need to be performed to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06682 | Date: 10/14/2020