

Inspection Photos  
Operator: Logos Operating  
API: 067-05363  
Date: 10/13/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass, sand dropseed, and sagebrush. Weeds such as Russian thistle and cheatgrass present.





Photo 3. View of stormwater controls installed in the northern project area. The up-slope wattle is full of sediment and needs maintenance. Weed debris needs to be removed.





Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland with and understory of sagebrush, squirreltail, Indian ricegrass, and mixed forbs.