

Inspection Photos

Operator: BP America
API: 067-09482
Date: 10/13/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with crested wheatgrass, sand dropseed, and western wheatgrass. Russian knapweeds are scattered here.




Photo 3. View of the northern fill slope from the northwestern corner facing eastward. Scattered Russian knapweeds also observed here.



Photo 4. Closeup view of Russian knapweeds within the western project area. Approximately 500 individuals observed.



Photo 5. View of reference area vegetation comprised of dryland grass field with western wheatgrass and crested wheatgrass in a dormant vegetative condition at this time.