

Inspection Photos

10/12/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334087

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 334087



Photo 1: Photo taken from the east end of the Location, facing southwest. Photo shows overview of the Location. Photo shows interim reclamation pursuant to 1003.b has not been conducted on the Location.



Photo 2: Photo taken from the east end of the Location, facing northwest. Photo shows overview of the Location. Photo shows interim reclamation pursuant to 1003.b has not been conducted on the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC # 10456

Location ID: 334087



Photo 3: Photo taken from the southwest end of the Location, facing north. Photo shows overview of the Location. Photo shows interim reclamation pursuant to 1003.b has not been conducted on the Location.



Photo 4: Photo taken from the southwest end of the Location, facing east. Photo shows overview of the Location. Photo shows interim reclamation pursuant to 1003.b has not been conducted on the Location.