

Inspection Photos

API: 071-09178

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos




Photo 1. Facing southwest toward the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 2. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 3. Facing west along access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 4. Facing northwest toward the cut slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing southwest toward the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 6. Facing south toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 7. Facing northeast toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing north toward the location. The cut slope is estimated to be 70 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09178 | Date: 10/8/2020