

Inspection Photos

API: 071-07791

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing northwest toward the beginning portion of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 2. The culvert along the access road is filled in with sediment causing erosion down the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 3. The road crosses the canyon bottom which creates a dam across the canyon. The culvert is filled in with sediment shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos




Photo 4. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing northeast along the access road. The culvert is filled in with sediment shown at red arrow. Rocks have fallen on the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 6. Facing east along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 7. Facing east toward the location. The location has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 8. There is erosion rilling along the slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 9. Facing southwest toward the location.



Inspection Photos



Photo 10. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020

Inspection Photos



Photo 11. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07791 | Date: 10/8/2020