

Inspection Photos

API: 071-07689

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07689 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing south toward the location at east side of the rod. Vegetation has reestablished within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07689 | Date: 10/8/2020

Inspection Photos



Photo 2. Facing north toward the location. Vegetation has reestablished within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07689 | Date: 10/8/2020

Inspection Photos



Photo 3. Facing north at the location on the west side of the road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-07689 | Date: 10/8/2020

Inspection Photos



Photo 4. There is an erosion channel that is directed down toward the road from the location. This area needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07689 | Date: 10/8/2020