

Inspection Photos

API: 071-07136

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/14/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 1. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 2. The pig launcher remains near the location and has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 4. Facing south toward the location. Areas of the location were resloped and seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 5. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 6. Facing southwest at the location. This area was recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 7. There is a rock riprap swale installed at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020

Inspection Photos



Photo 8. South side of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07136 | Date: 10/14/2020