

Inspection Photos
Location Name: Sigg 28-11K2
Location ID: 330021



Photo 1 WH sign

Photo 2 weeds overgrown around WH

Inspection Photos
Location Name: Sigg 28-11K2
Location ID: 330021



Photo 3 Weeds overgrown around wellsite and unused equipment

Photo 4 weeds overgrown around Horizontal Heated Separator.

Inspection Photos
Location Name: Sigg 28-11K2
Location ID: 330021




Photo 5 Gas Meter Run

Photo 6 Card in meter house indicates current calibration

Inspection Photos
Location Name: Sigg 28-11K2
Location ID: 330021



Photo 7 unused equipment by the Gas Meter Run

Photo 8 TB signs

Inspection Photos
Location Name: Sigg 28-11K2
Location ID: 330021




Photo 9 weeds overgrown in and on the TB berm

Photo 10 weeds overgrown in and on the TB berm