

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402514375

Date Received:

10/19/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kristina Geno

720-929-6824

Kristina_Geno@Oxy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697001704

Inspection Date: 07/23/2020

FIR Submit Date: 07/23/2020

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 311483

Location Name: STAR O-64N67W Number: 15SESE County: _____

Qtrqr: SESE Sec: 15 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.308400 Longitude: -104.871530

FACILITY - API Number: 05-123- -00 Facility ID: 311483

Facility Name: STAR O-64N67W Number: 15SESE

Qtrqr: SESE Sec: 15 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.308400 Longitude: -104.871530

CORRECTIVE ACTIONS:

2 CA# 140761

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 10/26/2020

Response: CA COMPLETED

Date of Completion: 10/06/2020

Operator Comment: The STAR 0 15-9 (API # 05-123-23278) had an MIT performed 10/6/2020. Form 21 document # 402513799

COGCC Decision: _____

COGCC
Representative:

3 CA# 140762

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 10/26/2020

Response: CA COMPLETED

Date of Completion: 10/06/2020

Operator Comment: The STAR 0 15-10 (API # 05-123-23279) had an MIT performed 10/6/2020. Form 21 document # 402513907

COGCC Decision:

COGCC
Representative:

4 CA# 140763

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 10/26/2020

Response: CA COMPLETED

Date of Completion: 10/06/2020

Operator Comment: The STAR 0 15-23 (API # 05-123-23264) had an MIT performed 10/6/2020. Form 21 document # 402513948

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: MITs for all three wells were performed 10/6/2020.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Callie Fiddes

Signed:

Title: Regulatory Analyst

Date: 10/19/2020 6:12:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files