

Inspection Photos
Location Name: Razor 11E PAD
Location ID: 435245



Photo 1 – PAD Sign at Entrance



Photo 2 – North Wellheads



Inspection Photos
Location Name: Razor 11E PAD
Location ID: 435245




Photo 3 – Razor 11E-0201A missing Wellhead Sign



Photo 4 – South Wellheads

