

Final Reclamation Inspection

October 13, 2020

Operator: HRM RESOURCES II LLC - 10548

Location ID: 319846

Inspection Document #: 697502077

Weld County, CO

NENW Section 2 T2S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MARTIN #1
Location ID: 319846



Photo 1. Photo taken from the western location, facing West. Photo illustrates the Operator has failed to remove all equipment (i.e, riser).

Inspection Photos
Location Name: MARTIN #1
Location ID: 319846



Photo 2. Photo taken from the eastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: MARTIN #1
Location ID: 319846



Photo 3. Photo taken from the northern location, facing South. Photo illustrates the location does not meet Rule 1004 standards. The location consists mostly of Curlycup gumweed.

Note: it appears the surface owner is storing equipment and trash.