

Final Reclamation and Stormwater Inspection

October 13, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 319834

Inspection Document #: 697502081

Adams County, CO

SWNE Section 35 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BOX ELDER FARMS 32-35 #4 (1-66)
Location ID: 319834



Photo 1. Photo taken from the associated offsite tank battery location, facing North. Photo illustrates the Operator has failed to remove all equipment. Also, Operator has failed to control weeds.

Inspection Photos

Location Name: BOX ELDER FARMS 32-35 #4 (1-66)

Location ID: 319834



Photo 2. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the Operator has failed to remove all equipment.

Inspection Photos
Location Name: BOX ELDER FARMS 32-35 #4 (1-66)
Location ID: 319834



Photo 3. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the Operator has failed to control weeds.

Inspection Photos
Location Name: BOX ELDER FARMS 32-35 #4 (1-66)
Location ID: 319834



Photo 4. Photo taken from the associated offsite tank battery location, facing East. See comments under Photo 3.

Inspection Photos

Location Name: BOX ELDER FARMS 32-35 #4 (1-66)

Location ID: 319834



Photo 5. Photo taken from the associated offsite tank battery location. Photo illustrates Operator has failed to control weeds (i.e., puncture vine).

Inspection Photos

Location Name: BOX ELDER FARMS 32-35 #4 (1-66)

Location ID: 319834



Photo 6. Photo taken from the associated offsite tank battery location. Photo illustrates germination of desirable grass species. Germination was not evident throughout the location and will likely require additional reclamation activities.

Inspection Photos
Location Name: BOX ELDER FARMS 32-35 #4 (1-66)
Location ID: 319834



Photo 7. Reference photo taken from the associated offsite tank battery location, facing Northwest. Photo illustrates the adjacent reference areas consists mostly of Sand dropseed.

Inspection Photos

Location Name: BOX ELDER FARMS 32-35 #4 (1-66)

Location ID: 319834



Photo 8. Photo taken from the well location, facing West. Photo illustrates all equipment has been removed from the well location. Well location is now part of a new housing development.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502081

Inspection Photos

Location Name: BOX ELDER FARMS 32-35 #4 (1-66)

Location ID: 319834



Photo 9. Photo taken from the well location, facing East. See comments under Photo 8.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502081