

Inspection Photos
Operator: BP America
API: 067-07165
Date: 10/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass and smooth brome.



Photo 3. View of the southern project area from the southeastern project area facing westward.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with gambel oak, western wheatgrass, prairie junegrass, and Oregon grape in the understory.



View of closed gate after exiting location.