

Inspection Photos
Operator: BP America
API: 067-07203
Date: 10/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of the western project area from the southwestern corner facing northward. Stormwater BMPs are installed and appear to be functioning at this time.



Photo 4. View of reference area vegetation comprised of ponderosa pine woodland with gambel oak, western wheatgrass, prairie junegrass, and Oregon grape in the understory.