

Construction and Stormwater Inspection

October 22, 2020

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 458635

Inspection Document #: 697502099

Weld County, CO

NWNE Section 22 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Blue Teal /Pad
Location ID: 454414



Photo 1. Photo taken from the eastern location, facing West. Photo illustrates the Operator is in process of salvaging topsoil. However, Operator has failed to install stormwater BMPs prior to starting topsoil salvage operations.

Inspection Photos
Location Name: Blue Teal /Pad
Location ID: 454414



Photo 2. Photo taken from the eastern location, facing South. Photo illustrates the Operator has failed to install stormwater BMPs prior to starting topsoil salvage operations.

Inspection Photos
Location Name: Blue Teal /Pad
Location ID: 454414



Photo 3. Photo taken from the northeastern location, facing West. Photo illustrates the Operator has failed to install stormwater BMPs prior to starting topsoil salvage operations.