

Grizzly Operating Kaufman 6 Location # 418772



location



location

Grizzly Operating Kaufman 6 Location # 418772



Oct 23, 2020 at 9:36:59 AM
+39.515958,-107.614707 ±26.77m
COGCC

location



Oct 23, 2020 at 9:45:31 AM
+39.515999,-107.614980 ±4.81m
COGCC

location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Kaufman 6
Location # 418772**



Broken unused equipment



Broken unused equipment



**Grizzly Operating
Kaufman 6
Location # 418772**



Berm needs maintained



Sediment migration/choking out vegetation



**Grizzly Operating
Kaufman 6
Location # 418772**



Sediment migration/choking out vegetation



Sediment migration/choking out vegetation



**Grizzly Operating
Kaufman 6
Location # 418772**



Ditch from pad leading to the sediment migration



Old waddle at bottom of ditch failing



**Grizzly Operating
Kaufman 6
Location # 418772**



Check dam bags



Check dam bags



**Grizzly Operating
Kaufman 6
Location # 418772**



Check dam bags



Check dam bags

