

Inspection Photos
Location Name: WPU-36 1V-H1
Location ID: 436485



Photo 1. Overview of location taken at entrance facing west.



Inspection Photos
Location Name: WPU-36 1V-H1
Location ID: 436485



Photo 2. No wellhead sign.



Photo 3. Deadmen not marked.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: WPU-36 1V-H1
Location ID: 436485



Photo 4. Stained soil on location.



Photo 5. Stained soil on location.



Inspection Photos
Location Name: WPU-36 1V-H1
Location ID: 436485



Photo 6. Unlabeled tank.



Photo 7. Stained soil on location.

