

**Inspection Photos**  
**Location Name: Dwinell 4**  
**Location ID: 324593**



**Photo 1. Overview of location taken at entrance facing west.  
Freshly disturbed soil with no stormwater controls.**

