



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

SW Rangely 2-18-1-2

API: 05-103-09498

Inspection: 700403902



39.96582, -108.88308, 6133.0ft, 32°
10/26/2020 03:26:38 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Tank.

SW Rangely 2-18-1-2

API: 05-103-09498

Inspection: 700403902



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well with gas leak.

SW Rangely 2-18-1-2

API: 05-103-09498

Inspection: 700403902

