

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/21/2020

Submitted Date:

10/21/2020

Document Number:

679603406**FIELD INSPECTION FORM**Loc ID 329966 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250308	WELL	SI	08/01/2019	GW	123-18111	LUNDVALL 30-11H6	PA

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Disconnected gas meter. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	01/21/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 250308 Type: WELL API Number: 123-18111 Status: SI Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITIONComment: PA  
Form 6(S) DOC#: 402431891(in process) in well fileCorrective Action:  Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p><b>**Weather Conditions: sunny, dry ground</b></p> <p>On Wednesday, October 21, 2020 at approximately 12:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at LUNDVALL 30-11H6 (Noble Energy), at location #: 329966 in WELD COUNTY Colorado.</p> <p>While there, I observed a plugged and abandoned wellhead.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. There is a disconnected gas meter on location. Remove to comply with Rule 603.f. (Corrective Action Date: January 21, 2020) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	10/21/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402515920	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274905">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274905</a>
679603407	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274903">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5274903</a>