

Inspection Photos
Location Name: Stoddard 33-30
Location ID: 423933



Photo 1. Overview of location taken facing northeast.

Inspection Photos
Location Name: Stoddard 33-30
Location ID: 423933



Photo 2. Stained soil at pump jack.



Photo 3. Tubing stored at wellhead.

