

Inspection Photos

10/23/2020

Operator: GORDON ENGINEERING INC -
34720

Location ID: 312386
Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312386



Photo 1: Photo taken from the west end of the well site, facing east. Photo shows well marker.



Photo 2: Photo taken from the south end of the Location. Photo shows stained/impacted soils on well site.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312386



Photo 3: Photo taken from the south end of the Location. Photo shows stained/impacted soils on well site.



Photo 4: Photo taken from the south end of the Location. Photo shows stained/impacted soils on well site.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312386



Photo 5: Photo taken from the access road. Photo shows final reclamation of the access road has not been completed.



Photo 6: Photo taken from the access road. Photo shows final reclamation of the access road has not been completed.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 312386



Photo 7: Google earth aerial imagery. Photo shows access road (yellow line) leading to the location requiring reclamation.