

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/30/2020

Submitted Date:

10/30/2020

Document Number:

699802028

**FIELD INSPECTION FORM**

Loc ID 450760	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 24 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1401 SEVENTEENTH STREET #1401 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450749	WELL	PR	07/01/2018		077-10382	Nichols 0994-24-12W	PR
450750	WELL	PR	09/01/2018		077-10383	Nichols Federal 0994-24-20E	PR
450752	WELL	PR	07/01/2018		077-10385	Nichols 0994-24-12E	PR
450753	WELL	PR	08/01/2018		077-10386	Nichols Federal 0994-24-18E	PR
450754	WELL	PR	07/01/2018		077-10387	Nichols 0994-24-11W	PR
450755	WELL	PR	08/01/2018		077-10388	Nichols 0994-24-17W	PR
450756	WELL	PR	09/01/2018		077-10389	Nichols Federal 0994-24-21E	PR
450757	WELL	PR	07/01/2018		077-10390	Nichols 0994-24-10E	PR
450758	WELL	PR	08/01/2018		077-10391	Nichols 0994-24-18W	PR
450759	WELL	PR	08/01/2018		077-10392	Nichols 0994-24-15E	PR
450761	WELL	PR	09/01/2018		077-10393	Nichols Federal 0994-24-19E	PR
450762	WELL	PR	08/01/2018		077-10394	Nichols Federal 0994-24-17E	PR
450763	WELL	PR	07/01/2018		077-10395	Nichols 0994-24-10W	PR
450764	WELL	PR	08/01/2018		077-10396	Nichols 0994-24-13E	PR
450765	WELL	PR	07/01/2018	OW	077-10397	Nichols 0994-24-11E	PR
450766	WELL	PR	09/01/2018		077-10398	Nichols 0994-24-19W	PR
450767	WELL	PR	10/01/2018		077-10399	Nichols 0994-24-21W	PR
450768	WELL	PR	08/01/2018	OW	077-10400	Nichols 0994-24-16E	PR

450769	WELL	PR	09/01/2018		077-10401	Nichols 0994-24-20W	PR
--------	------	----	------------	--	-----------	---------------------	----

**General Comment:**

## COGCC Inspection Report Summary

On Friday 10/30/20 at approximately 13:30 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at LARAMIE ENERGY LLC Nichols /24-07,  
Location #450760 in Mesa County Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Heated Separator	# 19		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 3		
Comment:	Chemical tanks by wellheads		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	450749	Type:	WELL	API Number:	077-10382	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450750	Type:	WELL	API Number:	077-10383	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450752	Type:	WELL	API Number:	077-10385	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450753	Type:	WELL	API Number:	077-10386	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450754	Type:	WELL	API Number:	077-10387	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450755	Type:	WELL	API Number:	077-10388	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450756	Type:	WELL	API Number:	077-10389	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450757	Type:	WELL	API Number:	077-10390	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	450758	Type:	WELL	API Number:	077-10391	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450759	Type:	WELL	API Number:	077-10392	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450761	Type:	WELL	API Number:	077-10393	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450762	Type:	WELL	API Number:	077-10394	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450763	Type:	WELL	API Number:	077-10395	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450764	Type:	WELL	API Number:	077-10396	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450765	Type:	WELL	API Number:	077-10397	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	450766	Type:	WELL	API Number:	077-10398	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	450767	Type:	WELL	API Number:	077-10399	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	450768	Type:	WELL	API Number:	077-10400	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Facility ID:	450769	Type:	WELL	API Number:	077-10401	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Sediment Traps						
		Gravel				
Check Dams						
		Check Dams				
		Rip Rap				
		Culverts				
Waddles						
Berms						
		Sediment Traps				
		Waddles				
		Berms				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Tank battery is located on adjacent location Nichols 24-06A location #450791. Refer to document #699801120 inspection conducted on 5/18/20.	depaoloc	10/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802029	Photos for Insp. #699802028	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281911#699802028">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281911#699802028</a>