

Inspection Photos

Location Name: MFS Federal 7-1

Location ID: 315594 Remediation Project Number: 11534

Inspection Date: October 13, 2020



MFS Federal 7-1 location.



Active pumpjack on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MFS Federal 7-1

Location ID: 315594 Remediation Project Number: 11534

Inspection Date: October 13, 2020



Tank battery where two additional soil borings will be advanced.



Monitoring well and unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MFS Federal 7-1

Location ID: 315594 Remediation Project Number: 11534

Inspection Date: October 13, 2020



Monitoring well within the tank battery secondary containment structure.



Additional tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources