

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/27/2020

Submitted Date:

10/30/2020

Document Number:

701001569**FIELD INSPECTION FORM**
 Loc ID 321861 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208259	WELL	PR	01/31/1996	OW	017-07194	BLEDSON 13-12	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Sticker on chemical drum		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to metal shed		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location and tank battery		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Mark II Lufkin 640		
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	Electric panel and cathodic rectifier in metal shed, chemical drum w/containment, electric circ pump by oil tanks, electric panel by tanks, electric transfer pump in meta shed at west treater		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:	1-Treater with metal shed on north side of water tank 1-Treater with metal shed on east side of tank battery		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		39.010460,-103.069020
Comment:	Water tank on south side of west treater				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	FIBERGLASS AST		39.010520,-103.069470
Comment:	Tanks on west side of location are disconnected and not in use				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	OTHER	STEEL AST		39.010830,-103.068480	
Comment:	Central tank battery for (Bledsoe 5-12, 13-12, Speaker 3-13)					
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)	550bbbls					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	208259	Type:	WELL	API Number:	017-07194	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Bledsoe 5-12, 13-12, Speaker 3-13) @ 39.010830/-103.068480								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001605	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282012
701001612	tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282013