

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 1: Pumpjack Sign



Photo 2: Pumpjack

Inspection Photos
Location Name: Black Hallow 8-67-16 #3H
Location ID: 428546



Photo 3: Unused Equipment



Photo 4: Unused equipment



Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546




Photo 5: No BBLs displayed



Photo 6: No BBLs displayed