

Inspection Photos
Location Name: Albert Cities East Pad
Location ID: 455319



Photo 1: Location sign at entrance



Photo 2: Wellheads



Inspection Photos
Location Name: Albert Cities East Pad
Location ID: 455319



Photo 3: Location of Not Drilled wellheads



Photo 4: Tank Battery



Inspection Photos
Location Name: Albert Cities East Pad
Location ID: 455319



Photo 5: Tanks do not contain labeling

