

Inspection Photos
Location Name: DF Ranch 20-22
Location ID: 410133



Photo 1 – Pumping Unit



Photo 2 – Unused Chemical Tank and Containment



Inspection Photos
Location Name: DF Ranch 20-22
Location ID: 410133



Photo 3 – Gas Engine has been removed



Photo 4 – Unused Wellhead parts



Inspection Photos
Location Name: DF Ranch 20-22
Location ID: 410133



Photo 5 – Wellhead Sign, unused Wellhead parts