

# Interim Reclamation Inspection

October 30, 2020

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 433082

Inspection Document #: 697502153

Morgan County, CO

NENW Section 18 T6N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location: Wickstrom 18 #2H  
Location ID: 433082




**Photo 1.** Photo taken from the entrance of location, facing South. Operator has failed to update the Operator Sign, which does not have an accurate emergency contact.



**Photo 2.** Photo taken from the northern well pad, facing South.

Inspection Photos  
Location: Wickstrom 18 #2H  
Location ID: 433082



**Photo 3.** Photo taken from the northern well pad, facing West. Photo illustrates interim reclamation have been performed. Appears weed management (i.e., mowing) is being conducted.



**Photo 4.** Photo taken from the northwestern well pad, facing South. See comments under Photo 3.

Inspection Photos  
Location: Wickstrom 18 #2H  
Location ID: 433082



**Photo 5.** Photo taken from the northeastern well pad, facing East. See comments under Photo 3.



**Photo 6.** Photo taken from the northeastern well pad, facing Southeast. See comments under Photo 3.