

Inspection Photos
Location Name: Canadian Slang Pad
Location ID: 449800



Photo 1: Location sign at entrance



Photo 2: Wellheads

Inspection Photos
Location Name: Canadian Slang Pad
Location ID: 449800



Photo 3: Unused/disassembled fencing



Photo 4: No Capacity or NFPA placard



Inspection Photos
Location Name: Canadian Slang Pad
Location ID: 449800



Photo 5: No NFPA placarding on crude oil tanks



Photo 6: No NFPA placarding on crude oil tanks

Inspection Photos
Location Name: Canadian Slang Pad
Location ID: 449800



Photo 7: No labeling on tank

