

Final Reclamation Inspection

November 3, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 317901

Inspection Document #: 697502166

Weld County, CO

SWNE Section 14 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: APOLLO #1
Location ID: 317901




Photo 1. COGCC GISOnline 2019 aerial imagery illustrating the well and tank battery location which has not been reclaimed.

Inspection Photos
Location Name: APOLLO #1
Location ID: 317901



Photo 2. Photo taken from the western well and tank battery location, facing North. Photo illustrates the Operator has failed to perform final reclamation activities per Rule 1004. Also, unmanaged weeds (Russian thistle and Kochia) were observed throughout the locations.

Inspection Photos
Location Name: APOLLO #1
Location ID: 317901



Photo 3. Photo taken from the eastern well and tank battery location, facing North. Photo illustrates the Operator has failed to perform final reclamation activities per Rule 1004 and remove debris.

Inspection Photos
Location Name: APOLLO #1
Location ID: 317901



Photo 4. Photo taken from the northeastern well and tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: APOLLO #1
Location ID: 317901



Photo 5. Photo taken from the northeastern well and tank battery location, facing East along the access road. See comments under Photo 1.