

Inspection Photos

Operator: BP America
API: 067-06610
Date: 11/2/2020



Photo 1. View of the project area from the southwestern corner facing center. Surface owner farm equipment stored east of the project area.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Consolidated berm in place.



Photo 3. View of the northern project area facing westward. Trailers parked next to tank within the project area need to be properly stored offsite.



Photo 4. View of the reference area comprised of irrigated grass field, currently grazed by cattle.