

Inspection Photos

11/02/2020

Operator: NONSUCH NATURAL GAS INC #
10163

Location ID: 324169
Garfield, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 1: Photo taken from the southeast end of the Location, facing west. Photo provides an overview of the Location and interim areas. Previous inspections required Operator to conduct additional interim reclamation activities, and to implement BMPs to stabilize the soils. Photo shows that additional reclamation and stabilization activities, and implementation of BMPs, do not appear to have been conducted.



Photo 2: Photo taken from the southeast end of the Location, facing north. See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 3: Photo taken from the east end of the Location, facing south. See comments under photo 1.



Photo 4: Photo taken from the north end of the Location, facing south. See comments under photo 1.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 5: Photo taken from the northwest end of the Location, facing southwest. Photo shows no additional reclamation activities appear to have been conducted. Photo also shows no BMPs have been installed to stabilize soil/slopes, prevent degradation and off-site sediment transport



Photo 6: Photo taken from the northwest end of the Location, facing west. See comments under photo 5.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 324169



Photo 7: Photo taken from the southwest end of the Location, facing west. See comments under photo 5.



Photo 8: Photo taken from the west end of the Location, facing west. See comments under photo 5.