

Inspection Photos

11/02/2020

Operator: NONSUCH NATURAL GAS INC #
10163

Location ID: 453726
Garfield, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-3 provide an overview of the production area from east, west to northwest.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



Photo 3: See comments under photo 1.



Photo 4: Photo shows 200 bbl condensate tank has been removed. Area does not appear needed for production and is now subject to 1003 interim reclamation

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 453726




Photo 5: Photo shows meter shed on Location. COGCC Records show meter shed is active and associated with the CSOC 697-14 1 well, API #045-07948

Photo 6: Photo shows separator equipment on Location. It is unclear to the COGCC at to what the equipment's current use is on the Location, and if equipment is considered active.

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC # 10163
Location ID: 453726



Photo 7: Photo shows methanol tank on the Location. It is unclear to the COGCC as to what the equipment's current use is on the Location, and if equipment is considered active.



Photo 8: Photo shows unused pipe equipment stored behind the methanol tank.