

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851



Photo #2184 from entrance to location.



Photo #2185 from entrance to location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /7NWSE

Location ID: 323851



Photo #2186 Multiple places with debris on location.