

Final Reclamation Inspection

November 3, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 331212

Inspection Document #: 697502179

Weld County, CO

SENE Section 12 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-LOT HOLDINGS #8-12
Location ID: 331212



Photo 1. Photo taken from the well location, facing Northwest. Photo illustrates the location is now part of a park owned by the Town of Milliken (CENTENNIAL COOPERATIVE PARK RPLT B B1 L2).

At the time of this inspection, no noxious weed issues were observed and no stormwater erosion issues were observed.

Inspection Photos
Location Name: HSR-LOT HOLDINGS #8-12
Location ID: 331212



Photo 2. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HSR-LOT HOLDINGS #8-12
Location ID: 331212



Photo 3. Photo taken from the associated offsite tank battery, facing South. See comments under Photo 1.