

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Sediment build up at corner of access and main road.



CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Contents faded.



No NFPA label on methanol tank.



CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Loose lid on unbackfilled rat hole.



Shovel used to check for backfill.

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Sediment buildup in diversion ditch.



Sediment build up in check dam.

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



**Sediment for diversion ditch moving on to
county rd..**

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Sediment buildup and movement at pig station.

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



Sediment covering culvert inlet.



Culvert outlet packed off.

CAERUS PICEANCE LLC
KM C08 799
Location ID: 423633



**Sediment moving on to access road and
blocking flow of drainage ditch.**