

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2020

Submitted Date:

10/30/2020

Document Number:

696302605

FIELD INSPECTION FORM

Loc ID 418696 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418696	LOCATION	AC			-	DF Ranch PC GK 17-99HZ Tank	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	West Tank Battery 17-34 - SE Crude Oil Tank and Produced Water Tank missing Capacity. See Photos		
Corrective Action:	Comply with Rule 210.d.	Date:	11/30/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	DF Ranch 17-99HZ Tank Battery (East TB) Unmarked Risers at Gas Meter House and West of Treater Shed. See Photos		
Corrective Action:	Comply with Rule 603.f.	Date:	11/06/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	FIBERGLASS AST		,
Comment: DF Ranch 17-34 Tank Battery (West)					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	FIBERGLASS AST		,
Comment: DF Ranch 17-99HZ Tank Battery (East)					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:		Shares berm with the Crude Oil Tanks				
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,	
Comment:		DF Ranch 17-34 Tank Battery (West)				
Corrective Action:						Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:				Shares berm with the Crude Oil Tanks	
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLS	STEEL AST		40.921410,-104.237040
Comment:				DF Ranch 17-99HZ Tank Battery (East)	
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLS	STEEL AST		40.921640,-104.238510
Comment:				DF Ranch 17-34 Tank Battery (West)	
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 418696 Type: LOCATION API Number: - Status: AC Insp. Status: AC**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Both Tank Batteries Shut-In at the time of this Inspection.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Winter Conditions, snow covered ground at the time of Inspection. Unmarked Risers and South 500 BBL H2O and Crude Oil Tanks Missinf NFPA Labels on East 17-99HZ Tank Battery. Crude Oil and Produced Water Tanks missing Capacity labels on West 17-34 Tank Battery.	petrie	10/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402523007	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281495
696302610	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281493