

Inspection Photos

Loc#436485

Operator: PRM

Inspection Number: 692402629

Inspection Date: 10/23/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

October 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PRM WPU Loc#436485



Photo#2:

Overview of Location from top of Cut Slope to Southeast.

October 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PRM WPU Loc#436485



Photo#3:

View along North side Fill Slope, showing initiation of erosion.

October 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PRM WPU Loc#436485



Photo#4:
Initiation of erosion on Fill Slope.



Photo#5:
Initiation of erosion on Fill Slope.

October 23, 2020



Photo#6:

View along Cut Slope and sediment from cuttings area migrating onto Location.

October 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PRM WPU Loc#436485