

Inspection Photos
Location Name: Lost Creek 3-62-824H
Location ID: 450093



Photo 1 – Wellhead



Photo 2 – Tank Battery



Inspection Photos
Location Name: Lost Creek 3-62-824H
Location ID: 450093



Photo 3 – Compressor



Photo 4 – Heater Treater, Separator, ECD

Inspection Photos
Location Name: Lost Creek 3-62-824H
Location ID: 450093



Photo 5 – Tank Battery Sign



Photo 6 – Produced Water Tank missing – NFPA, Content, and Capacity