

Grizzly Operating Leg Location # 323932



location



location



Grizzly Operating Leg Location # 323932



location



Sediment migration

**Grizzly Operating
Leg
Location # 323932**



Sediment migration arrow is pointing at fence panel



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Leg
Location # 323932**



Fence panel next to sediment migration in photos 4 and 5

