

Inspection Photos
Location Name: UPRR 24 PAN AM B 1
Location ID: 319918



Pic 1



Pic 2

Inspection Photos
Location Name: UPRR 24 PAN AM B 1
Location ID: 319918

Oct 29, 2020 at 1:14:47 PM
39.872094,-104.541950
Bennett CO 80102
United States
COGCC



Pic 3

Oct 29, 2020 at 1:15:05 PM
39.872179,-104.541892
Bennett CO 80102
United States
COGCC



Pic 4 unused equipment tubing

Inspection Photos

Location Name: UPRR 24 PAN AM B 1

Location ID: 319918

Oct 29, 2020 at 1:15:25 PM
39.872322,-104.542222
Bennett CO 80102
United States
COGCC



Pic 5 unused equipment

Oct 29, 2020 at 1:15:53 PM
39.872358,-104.542605
Bennett CO 80102
United States
COGCC



Pic 6 unused equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: UPRR 24 PAN AM B 1
Location ID: 319918

Oct 29, 2020 at 1:16:08 PM
39.872364,-104.542863
Bennett CO 80102
United States
COGCC




Pic 7 unused equipment

Oct 29, 2020 at 1:16:22 PM
39.872308,-104.542961
Bennett CO 80102
United States
COGCC



Pic 8 unused equipment

Location ID: 319918



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources