

Inspection Photos
Location Name: State of Colorado P1
Location ID: 16321



Pic 1



Pic 2

Inspection Photos

Location Name: State of Colorado P1

Location ID: 16321

Nov 5, 2020 at 1:25:56 PM
39.915974,-104.602994
2301-12459 Watkins Rd
Hudson CO 80642
United States
COGCC



Pic 3 ECD flaring produced gas on location

Nov 5, 2020 at 1:26:23 PM
39.915974,-104.602994
2301-12459 Watkins Rd
Hudson CO 80642
United States
COGCC



Pic 4 stained soil under ECD line

Inspection Photos
Location Name: State of Colorado P1
Location ID: 16321



Pic 5 stained soil under ECD



Pic 6 Gas meter run De-commissioned, gas on location flared with ECD.

Inspection Photos
Location Name: State of Colorado P1
Location ID: 16321

