

Final Reclamation Inspection

November 5, 2020

Operator: HIGHPOINT ENERGY LLC - 10544

Location ID: 424350

Inspection Document #: 697502184

Weld County, CO

SENW Section 22 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: 392 VENTURES PAD /CN-22

Location ID: 424350



Photo 1. Photo taken from the entrance of location, facing West. Photo illustrates equipment that was identified in the previous inspection has not been removed.

Inspection Photos

Location Name: 392 VENTURES PAD /CN-22

Location ID: 424350



Photo 2. Photo taken from the northeastern location on 2/25/2020, facing East. Photo illustrates unused equipment left at location.

At the time of the inspection conducted on 11/5/2020, this equipment remains.

Inspection Photos

Location Name: 392 VENTURES PAD /CN-22

Location ID: 424350



Photo 3. Photo taken from the northeastern location on 2/25/2020, facing East. Photo illustrates unused equipment left at location.

At the time of the inspection conducted on 11/5/2020, this equipment remains.

Inspection Photos

Location Name: 392 VENTURES PAD /CN-22

Location ID: 424350



Photo 4. Photo taken from the northern location on 2/25/2020, facing West. Photo illustrates spills left behind that have not been cleaned up.

At the time of the inspection conducted on 11/5/2020, the entrance was locked so COGCC staff could not verify whether this was