

Inspection Photos

Loc#335520

Operator: Terra

Inspection Number: 692402632

Inspection Date: 10/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry.

October 20, 2020



Photo#2:
Kochia growth on areas no longer needed for use.

October 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Laramie Loc#335520



Photo#3:
East Cut slope.



Photo#4:
East Cut slope.

October 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Laramie Loc#335520



Photo#5:
Degrading traffic area.



Photo#6:
Tanks Not In Service.

October 20, 2020