

Inspection Photos

Loc#324144

Operator: Mustang

Inspection Number: 692402005

Inspection Date: 3/12/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View of Location from entry to East and Anchor Marker needing bright color.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Resources Loc#324144



Photo#2:
Unused area on West side of where re-vegetation efforts may have been conducted.



Photo#3:
Unknown Risers/Lines.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Resources Loc#324144