

Inspection Photos
Loc#334940
Operator: Caerus
Inspection #: 692402650
Inspection Date: 10/30/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to West.

October 30,, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzal Loc#334940



Photo#2:

Stormwater tunneling through sink holes off ditches and pooling areas.



Photo#3:

Stormwater tunneling through sink holes off ditches and pooling areas.

October 30,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334940