

BP L48 San Juan



V2 Compliance Follow Up Form

18160700450

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201030-18160700450

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Oct 30, 2020 3:03:55 PM MDT


91 S Skylane Dr, Durango, CO 81303, USA

Oct 30, 2020 3:03:30 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	colen@horizonenvservices.com
Date	Oct 30, 2020
Well Name	FEDERAL LAND BANK GAS UNIT G 2
Location Name (Other)	Federal land bank G4
API Number	50670900400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other
Photo of first corrective action completed	



Completed work description Corrective
 Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated Russian knapweed populations

Photo of third corrective action completed



Completed work description of corrective action 3

treated Russian knapweed populations

Photo of fourth corrective action completed



Completed work description

treated Russian knapweed populations

Completed work description of corrective action 4

treated Russian knapweed

Additional photos



Additional photos

**Additional photos****Completed work description****Summary of all work completed**

treated Russian knapweed populations

previous treatment dates 6/16/16, 7/25/17,
7/17/18, 6/12/19, 5/27/19